






Altamont Pass Wind Resource Area Repowering Program













Figure 3.6-3 Probabilistic Seismic Hazards Map (Seismic Shaking)











Figure 3.6-5
Landslides Causing Damage to the
Built Environment during Heavy Rain Event in 1998





Altamont Pass Wind Resource Area Repowering Program

Figure 3.6-6 Soil Associations Map